




CREWS TO CLOSE RIGHT LANE OF EASTBOUND WESTSIDE AT INTERSECTION WITH NM 528 THROUGH ABOUT AUGUST 15, 2022

Update as of Thursday, July 28, 2022

CONTACT for questions and more information:

Patti Watson, 505-269-9691 cell; 505-245-3134 office; pattiw@cwastrategic.com

NEW: Beginning today, Thursday, July 28 or tomorrow, Friday, July 29, the right lane allowing eastbound traffic on Westside to head southbound on NM 528 will be **CLOSED** so crews can work on ramps at the southwest corner of the intersection. Two lanes of eastbound traffic will be open – a thru/left-hand turn lane and a thru/right-hand turn lane.



Ongoing Traffic Impacts

- There are various right lane closures on northbound and southbound Golf Course Road north and south of Westside Blvd.
- Westbound traffic on Westside Blvd is reduced to one lane between NM 528 and Golf Course Rd.
- Eastbound traffic on Westside Blvd is reduced to one lane between Golf Course Rd and NM 528.
- Traffic on La Sierrita Rd and 7 Bar Loop Rd is able to turn right and head eastbound on Westside Blvd, but is **NOT** able to turn left and head westbound on Westside Blvd. Motorists can access westbound Westside Blvd by taking 7-Bar Loop Rd south to Driftwood Ave, heading west on Driftwood Ave, then north on Golf Course Rd. Westbound motorists on Westside Blvd can access La Sierrita or 7 Bar Loop Rd via Golf Course Rd south to Driftwood Ave, then east on Driftwood Ave to 7 Bar Loop Rd.

Regular work hours are **Mon.-Fri., 6:30 a.m.-5 p.m.**, although the contractor may work longer hours or on weekends if needed. **Saturday work is planned for the next few weeks. All construction is weather permitting and subject to change without notice.**